

2008

CASE HISTORY: DURABILITY OF HDPE MEMBRANE

Project Title:	Pond Desilting at Penfold Garden
Period:	Oct 1993 – Oct 2008
Client:	The Hong Kong Jockey Club
Supplier:	G and E Company Limited
Works:	Waterproofing System
Materials:	HDPE Membrane



Laying Down of HDPE Membrane Waterproofing System at the Bottom of Pond, Sep 1993



Desilting of Pond, July 2003. Minor Repair Works were Necessary After Bobcat Operation.



Repairing the Membrane, Sep 2005. Minor Repair Works were Necessary After Bobcat Operation.

2008

CASE HISTORY: DURABILITY OF HDPE MEMBRANE



Before Desilting, Sep 2005



Repairing of HDPE Membrane, Sep 2005



Addition of Sediment Separation Bund Repair Work After Construction Work in Existing HDPE Membrane.